

## Study on Deviations and Settlements of Rails and Its Maintenance in Broad Gauge Railway Track

<sup>1</sup>dr.G.Venkata Rao <sup>2</sup>mr.K.S.B.Prasad

<sup>1</sup>Professor, Department of Civil Engineering VIIT, Duvvada, Visakhapatnam

<sup>2</sup>Asst.Professor, Department of Civil Engineering GMRIT,Rajam,Srikakulam

Corresponding Author: dr.G.Venkata Rao

### ABSTRACT

The deviation of Rail track is a problem that had happened on Rail road systems. This resulting in the noise, vibrations, fuel consumption and taking more time. Since small changes in the aligned track will result significant change in the total cost of travel. For this, there are manual methods however it is more complex one and needs more manpower. So now a days instrumental and machinery utilization becomes more faster and cost effective to settle various issues on railway track. The aim of this paper is to identify the location with oms, direction and amount of deviation occurred on the Railway track. The Methodology of this study involves collection of reduced level's for 40km and deviations and settlements which are observed through the selected track and then these Horizontal deviations and vertical settlements are further analysed to calculate Track Geometry Index (TGI) with the help of Analytical approach called track degradation Concept. The basic tests on soil and a few descriptions about the Embankment soil and Ballast is investigated and are compared with the Recommended specifications of Indian Railway. TGI value obtained is 51.6 which comes under second condition that is need for basic maintenance as specified by Indian railways

**KEYWORDS:** Track ; Deviation ; Rail ; Geometry Index and Alignment.

Date of Submission: 06-04-2018

Date of acceptance: 21-04-2018

### I. INTRODUCTION

Railway track is one of the main railway facilities and the basis for train operations. Safe, stable, and uninterrupted train operations primarily depend on continuous track regularity [19]. Rail traffic accidents due to derailments are nowadays become a common problem and lead problematic to Indian railways. Railway track plays a base element in railway system and is greatly and directly influences on safety and cost efficiency. Investigations have been carried out for the identification of problems and are associated with track degradation process, which causes a low level of safety, which causes traffic accidents have become a social-economical problem. Indian Railway always improves the condition of the track for its good operating, but the problems in a single kilometer of the track will result in the lakhs to be repaired. Hence the total (LCC) Life cycle cost will be in crores [15]. In present study, as the load goes on increasing and the design is old, but no improvements done in last five years for beneath layers of embankment and the changes in seasonal effects and shows impact on embankment stability, which results in causing deviations. However, due to changing temperatures and the resulting unstable mechanical properties of layers, considerable difficulties have been encountered.

Track degradation from Geometrical aspect is considered for analysis and adopted. This study deals with geometrical perspective of track degradation; twist deviation parameter is very much defined for tracks and its effects [1]. The roles of several parameters that influences railway track deterioration most, are examined and with a view to make railway track maintenance more effective and cost efficient [8]. TQI is a new parameter to get more information about track geometry and the track maintenance standard can be judged [9].

The present area considered for study purpose is East Coast Railway and surveyed for Vertical settlements and horizontal deviations. This paper tends to analyze the deviations of rails, and compares standards between field measurements and Design standards.

### II. PROBLEM DESCRIPTION

The deviations of Rails in a Railway track are an issues which are common in all Railways, that results in the vibrations, noise, fuel consumption and time taken. Since the small change in the alignment will result in

significant change in the total cost of travel. The problems in the 1km piece of the studied track is badly out of alignment, cross-level across the rails having rotted ties, consecutive ties where missed with spikes and having loose fish plates.

### III. STUDY AREA

The Vizianagaram – Bobbili Line is a Railway line is the part of the East Coast Railway of Indian Railways. It has a total distance of 50km from which the First 40km section has been taken for the study purpose. The area covered by this line (including branch lines) is rich in mineral resources, Coalfields, TPC power stations and Thermal and NTPC Power stations, NALCO, Vedanta Aluminium Limited and plant at Hirakud at another side of orissa. All the goods trains from these stations with heavy loads are expected to passes through this Line towards Visakhapatnam off south India. On at another side, the Vishakhapatnam Port started in 1933 carries its locomotives trains through this line towards Orissa. As this stretch carried a load of 6-10GMT/year but now it was increased to about 29GMT/year. Hence deviations and settlements are there from Vizianagaram to Bobbili site. These deviations and settlements are surveyed with the Total station and calculated its magnitude in ‘mm’.

### IV. METHODOLOGY

In this paper, the method to evaluate the track conditions such as deviations and settlements have been analyzed by track degradation concept. Settlements due to shrinkage of embankment and loads, which effect in sudden increment or decrement. Soil sample tests are conducted for the site condition where maximum deviation is occurred to access type and behaviour of soil and checked the limits as per Indian railway standards. The problematic zone is identified by oscillation measuring device (OMS) [14]. Condition of the railway track is accessed by track geometry index (TGI), which is based on the different geometry parameters such as Unevenness (UI), Twist (TI), Alignment (AI), Gauge (GI) over a stretch of 200 m. Based on TGI, the level of maintenance of track is assessed as per Indian railway standards [4].

TGI is evaluated by the below equation ( developed by Indian Railways) :

$$TGI = 2UI + TI + 6AI + GI/10$$

Where,

UI = Unevenness

TI = Twist

AI = Alignment

GI = Gauge

### V. CALCULATION OF DEVIATIONS AND SETTLEMENTS

The survey work gives the results on the behavior of the track geometry, which shows the track substructure resembling the failure condition in terms of shrinkage [13]. These deviations are calculated by importing the Total Station data into Autocad software.

In this study, a new parameter called deviation is defined, which is the difference of the actual alignment and the existing alignment on the different basis. The measurement limits have been calculated based on the twist measurement from Vizianagaram to Bobbili railway line sections, which are part of the East coast railway network. From the twist, twist deviation have been accessed for different speed and to geometry of the track shown in Table 1.

#### 5.1 *Horizontal deviations, Vertical settlements and OMS*

Horizontal deviations will occur due to lateral replacement of Rail cum sleeper from its original position. So there will be partial amount of deviations can be occurred. Among all the survey done for finding levels and alignment of the study track stretch, the maximum deviations are observed in the chainages 435, 440, 441, 445.

This following chainage graph shows the deviation in left and right direction from its center line for a single kilometer show as an example in below figure.1.




Fig. 1. Graph shows the twist deviation for a single kilometre length of track in a chainage at 426.

Following graph shows the average standard deviations occurred in the selected length of the track and is further calculated for mean deviation as shown in figure2.




Fig. 2. The Graph shows the twist deviation for all length of track as whole a single Km chainages from 427 to 453.

Vertical settlements are occurred due to the shrinkage of Embankment and loads, which affect sudden increment or decrement in its profiles in the length of the track. The following figure shows the vertical profile of a rail in its longitudinal direction at chainage of 428. Settlements occurred at chainage 441, 442 and the vertical elevations at chainage 428 only show as an example in this paper in figure.3. and there is a need for proper compaction of side slopes. Shrinkage of embankments is accessed based on soils tests conducted in the particular zone and their remarks are tabulated in table 2. The following table shows the laboratory tests conducted and the results obtained for the selected chainage.




Fig. 3. Vertical Elevations in Chainage 428

Settlements due to loads is accessed by OMS(Oscillation measuring device) at the chainages where there is sudden increment or decrement in speed of train occurs. The following table 1 shows the location, chainage speed and acceleration recorded in a travel while surveying from Vizianagram to Bobbili section.

Table. 1 Vertical and Lateral Acceleration observed through OMS

|                     |                        |
|---------------------|------------------------|
| SECTION:VBL- VZM    | OMS RUN NO :592        |
| LINE : DN           | DATE OF RUN: 06 Feb-15 |
| KM FROM: 427 to 464 | TH. LIMIT >= 0.15      |

| Kilometer | Distance(m) | ACCELERATION VALUE |               |              |
|-----------|-------------|--------------------|---------------|--------------|
|           |             | Vert. Accn.(g)     | Lat. Accn.(g) | Speed (Km/h) |
| 427       | 993.1       | 0.16               |               | 104.23       |
| 432       | 496.7       | 0.15               |               | 108.56       |
| 432       | 558.8       | 0.16               |               | 108.56       |
| 432       | 861.2       | 0.16               |               | 108.56       |
| 432       | 868.2       | 0.19               |               | 108.56       |
| 432       | 875.1       | 0.17               |               | 108.56       |
| 432       | 908.6       | 0.16               |               | 108.56       |
| 432       | 908.6       |                    | 0.15          | 108.56       |
| 432       | 920.1       |                    | 0.18          | 108.56       |
| 432       | 980.7       | 0.17               |               | 108.56       |
| 433       | 110.4       | 0.16               |               | 110.97       |
| 433       | 844.1       | 0.16               |               | 110.97       |
| 433       | 854.9       | 0.16               |               | 110.97       |
| 433       | 996.1       | 0.18               |               | 110.97       |
| 434       | 200.5       |                    | 0.17          | 99.12        |
| 434       | 364.9       | 0.16               |               | 99.12        |

As the observed OMS report is too lengthy in original format, the report was compressed as shown above. The problem zone was identified by the deviated values and oscillation measuring device. There are maximum deviations which are up to about 30mm maximum and chainages observed are 441, 442, 435 etc., but at a place of Ch: 441/2, a sudden increment in the profile of the vertical gradient has occurred and leading to Rail wheel burns.

**Table. 2 comparison of Soil Test results with Indian Railway recommendations.**

| S.No | Description   | Recommended by Indian Railways  | Existing on site | Remarks   |
|------|---|---|------------------|---|
| 1    | For BG topwidth double line                               | 10.82m  | 9.15m            | Less (Erosion)  |
| 2    | Bank offset   | 90cm  | 75cm             | Less (remoulded)  |
| 3    | Side slope  | 2:1   | 2.2:1            | Slips in bank slopes  |
| 4    | Extra wide bank   | 50cm  | 0                | Not provided  |
| 5    | LL (Liquid limit)   | Shouldn't be >35  | 8%               | Satisfied   |
| 6    | Ip (plasticity index)                                     | <10   |                  |   |
| 7    | Cu(Coefficient of uniformity)                             | >4 to 7   | 5.71             |   |
| 8    | Cc( coefficient of curvature)                             | 1 to 3  | 0.8              | graded gravel   |
| 9    | Gradation test- Single Blanket Layer over Embankment Fill | Cu > 4, 1 < Cc < 3, Fine Particles (size smaller than 75 microns) less than 50% | Same             | Well graded gravel or sandy gravel with little or no fines GW |
| 10   | MDD   | 90%   |                  |   |
| 11   | Fines agg <75µ  | Not more than 5%  | 2%               | Good  |
| 12   | CBR   | 3 to 8  | 9.2              | Good  |

As per the soil tests there is 50cm erosion in the embankment, and soil classified as a well graded gravel, and it is examined that 1m extra wide on the top of Embankment is not provided. Ballast quality and condition in the study stretch are as mentioned in the table 3.

**Table. 3. Comparison of IR Recommendations and site condition for Ballast before and after study**

| S.No | Description  | Recommended by Indian Railways                      | Existing on site   | Remarks  |
|------|--|---|--------------------|--|
| 1    | Size of the ballast  | 50mm  | 30 to 50mm         | Crushed due to loads   |
| 2    | Size and Gradation:<br><b>Size of the sieve:</b><br>65mm<br>40mm<br>20mm                               | 5% Max<br>40% to 60%<br>Should not be less than 98% | 0%<br>68.5%<br>95% | 10% reduction in contracted rates if retention on a 40 -mm square mesh Sieve is between 65% and 70%. |
| 3    | Depth of the Ballast cushion<br>(d) = $\frac{\text{Sleeper spacing} - \text{width of the sleeper}}{2}$ | 15 – 20 cm  | 19.8               | Less (Sleeper tends to settled to about 4cm)   |
| 4    | 'd' under Fish plates  | 30 cm   | 21.5 cm            | Less (crushed and shrinkage to 28% but limit is only 8%)   |
| 5    | Aggregate Abrasion   | 30% Max   | 36% on test        | Less (More dust Evaluation during traffic passage)   |

|   |                  |         |             |   |
|---|------------------|---------|-------------|---|
| 6 | Aggregate Impact | 20% Max | 28% on test | Less (Leads to reduction in thickness of Ballast Layer) |
| 7 | Water absorption | 1%      | 4% on test  | Moisture retains and leads to less life                 |

## VI. CALCULATION OF TRACK GEOMETRICAL INDEX

### 1.1. Issues with Twist Deviation Parameter

The Twist is occurred only in straight line and curve with theoretically constant cant, if there is an asymmetrical longitudinal fault of the track. There is a twist already built in for the sections with cant transitions, therefore if there is a longitudinal fault in this section it is larger, than in other sections of the track. In this case, the basic twist of the cant transition and the twist caused by the longitudinal fault are added together [1].

The twist deviation was calculated according to the below-mentioned formula. This is the difference between the averaged twist and the twist in the given point.

$$S_{ei} = S_a - S_i$$

Where:

$S_i$  : twist (mm);

$S_a$ : averaged twist in the averaging length (mm);

$S_{ei}$ : twist deviation.

Using twist deviation in order to solve the deviation problems is not new among railway professionals are using a similar parameter according to their standards. The main idea of the method is that the twist values are averaged over a given length and this value will be the new baseline [14]. The difference between this baseline and the twist values provide the new local geometry parameter called twist deviation. The research of this article was based on this method.

### 6.2. Track Geometry Index

Indian Railways has developed a formula to represent the quality of track called TGI. This model is based on the standard deviation of different geometry parameters over a stretch of 200m segment. TGI is calculated for each segment and the average value of such segments in every km gives the general TGI value. With respect to the effect of each geometry parameter on the ride quality, TGI has given different value for various geometry parameters as shown in the following formula [5]:

$$TGI = 2UI + TI + 6AI + GI/10$$

The TGI is an SD based index evolved by Indian Railway. TGI takes into account the index for different geometry parameters, assessing the track condition with respect to a range defined at one end by “best-maintained track” and at the other by ‘track needing urgent maintenance’. The index for individual parameters e.g., the gauge is worked out as follows [6].

$$GI = 100 * e^{\frac{SDm - SDN}{SDu - SDN}} / n$$

Where,

$SDm$  =SD of measured parameter;

$SD_N$  = SD value of newly laid track; and

$SDU$  =SD values for a track needing urgent maintenance.

$SDm$  (Standard deviation of measured Parameter) values is observed from field survey by total station and the average value is evaluated for every kilometer.  $SD_N$  7values for a newly laid track and  $SDU$  a track needing urgent maintenance are tabulated below as per railway standards.

**Table. 4. Standard deviation (SD) values [7] (Sadeghi & Asgarinejad, 2008)**

| Parameters | Length Chord | SD for newly laid track | SD values for urgent maintenance mm            |   |
|------------|--------------|-------------------------|--|---|
|            |              |                         | SD for maintenance with Max. speed >= 105 km/h | SD for maintenance with Max. speed = 105 km/h |
| Unevenness | 9.60         | 2.50                    | 6.2  | 7.2   |
| Twist      | 3.60         | 1.75                    | 3.8  | 4.2   |
| Gauge      | 1            | 1                       | 3.6  | 3.6   |
| Alignment  | 7.2          | 1.50                    | 3.0  | 3.0   |

**Table. 5. Calculation of Track Geometric Index**

| Track: VZM TO VBL        |                  | Track Geometry Index |               |          |          |
|--------------------------|------------------|----------------------|---------------|----------|----------|
| YEAR: 2015 Data          |                  |                      |               |          |          |
| Chainage                 | Mean(Sa)         | SD(Si)               | Sei = Sa - Si | e        | GI       |
| 427                      | 12.39            | 6.03                 | 6.360         | 8.067187 | 806.7187 |
| 428                      | 10.65            | 6.25                 | 4.400         | 8.981096 | 898.1096 |
| 429                      | 18.72            | 3.13                 | 15.59         | 1.960444 | 196.0444 |
| 430                      | 19.80            | 5.71                 | 14.09         | 6.901283 | 690.1283 |
| 431                      | 8.90             | 5.84                 | 3.060         | 7.353100 | 735.3100 |
| 432                      | 7.54             | 5.91                 | 1.630         | 7.608517 | 760.8517 |
| 433                      | 9.83             | 5.70                 | 4.130         | 6.867700 | 686.7700 |
| 434                      | 13.5             | 5.90                 | 7.600         | 7.571493 |          |
| 435                      | 10.10            | 3.41                 | 6.690         | 2.247360 | 224.7360 |
| 436                      | 9.7              | 4.7                  | 5             | 4.21658  | 421.658  |
| 437                      | 19.28            | 3.83                 | 15.45         | 2.758354 | 275.8354 |
| 438                      | 11.04            | 3.6                  | 7.44          | 2.465609 | 246.5609 |
| 439                      | 18.53            | 5.5                  | 13.03         | 6.229327 | 622.9327 |
| 440                      | 1.23             | 1.56                 | -0.33         | 0.911482 | 91.14825 |
| 441                      | 10.86            | 4.26                 | 6.6           | 3.402091 | 340.2091 |
| 442                      | 8.8              | 5.1                  | 3.7           | 5.125081 | 512.5081 |
| 443                      | 10.9             | 4.16                 | 6.74          | 3.240118 | 324.0118 |
| 444                      | 14.3             | 5.43                 | 8.87          | 6.020209 | 602.0209 |
| 447                      | 11.8             | 1.24                 | 10.56         | 0.779751 | 77.97511 |
| 448                      | 8.8              | 4.54                 | 4.26          | 3.899996 | 389.9996 |
| 449                      | 9.7              | 4.93                 | 4.77          | 4.717219 | 471.7219 |
| 450                      | 19.3             | 4.9                  | 14.4          | 4.64869  | 464.869  |
| 451                      | 20.6             | 5.613                | 14.987        | 6.58234  | 658.234  |
| 452                      | 10.08            | 5.12                 | 4.96          | 5.175327 | 517.5327 |
| 453                      | 7.7              | 3.7                  | 4             | 2.588865 | 258.8865 |
|                          |                  | 4.64252              | -4.64252      | 4.812769 | 481.2769 |
| <b>Obtained Value</b>    | <b>TI = 4.64</b> | <b>GI = 481</b>      |               |          |          |
| <b>Considered values</b> | <b>UI = 6.2</b>  | <b>AI = 3.0</b>      |               |          |          |

Therefore,

$$TGI = 2UI + TI + 6AI + GI/10$$

$$TGI = 2(6.2) + 4.64 + 6(3.0) + 481 / 10$$

$$= 51.6.$$

From the site work, the obtained TGI value is 51.6 but as per Indian Railway Specified the values is tabulated below [9].

**Table. 6. TGI Classification for Maintenance**

| S. No | TGI Value (Track Geometry Index) | Maintenance is requirement |
|-------|----------------------------------|----------------------------|
| 1     | TGI > 80                         | No maintenance required    |
| 2     | 50 < TGI < 80                    | Need basic maintenance     |
| 3     | 36 < TGI < 50                    | Planned Maintenance        |
| 4     | TGI < 36                         | Urgent Maintenance         |

As per above the table.6, the Value obtained 51.6 falls in the second condition within the limit of 50 < TGI < 80. So there is a need for basic maintenance of track from Vizianagaram to Bobbili section.

## VII. CONCLUSION

In this study, deviation is estimated, which is the difference of the actual alignment. The measurement limits have been calculated based on the twist measurement of several vizianagaram to bobbili railway line sections, which are part of the East coast railway network. Direction and amount of deviations occurred are recorded upto about 30mm Maximum and 5mm minimum. Twist deviations exceeding limits in each chainage is compared with Limits specified by IR and chainages such as 426, 431, 435 and 441 are recorded as maximum. Embankment top width had losses to about 750mm. Among all the survey accomplished for the calculation of levels and alignment, the maximum deviations observed in the chainages are 435, 440, 441 and 445. All the problems associated with the track such as deviations and settlements have been solved based on parameters and the obtained values are TI = 4.64, GI = 481, UI = 6.2, AI = 3.0. Based on the estimated Value of TGI which is 51, falls in the second condition within the limit of 50 < TGI < 80, there is a need for basic maintenance of track from Vizianagaram to Bobbili section.

## ACKNOWLEDGEMENTS

The Authors are thankful to the East Coast Railway for conducting the survey work from Vizianagaram to the Bobbili Section. Special thanks to Sr. Section Engineer Division, Gajapathinagaram Railway for his cooperation and support.

## REFERENCES

- [1]. Anita Ortelli and Tamas Mátrai “Twist deviation, as new track geometric measurements parameters for Hungarian railways” in Transport Research Arena 2014, Paris.
- [2]. Abdur Rohim Boy Berawi, “Improving Railway Track Maintenance Using Power Spectral Density”, Faculdade De Engenharia Universidade Do Porto, Aug 2013.
- [3]. N. Lalwani & B. P. Awasthi, “Track Monitoring”, IRICEN, Indian Railway Institute of Civil Engineering, March 2013.
- [4]. Abdur Rohim Boy Berawi, Raimundo Delgado and Rui Calçada, “Evaluating track geometrical quality through different Methodologies”, International Journal of Technology (2010).
- [5]. J. Sadeghi, “Development of Railway Track Geometry Indexes Based on Statistical Distribution of Geometry Data”, Journal of Transportation Engineering, Aug, 2010.
- [6]. Haitham M. Hawari and Martin H. Murray, “Effects of Train Characteristics on the Rate of Deterioration of Track Roughness”, Journal of Engineering Mechanics, March 2008.
- [7]. Sadeghi, J. & Askarinejad, H., 2008. Development of Improved Railway Track Degradation Models. International Journal of Structure and Infrastructure Engineering, Vol.3, Issue 4.
- [8]. J. Sadeghi and H. Askarinejad, “Influences of Track Structure, Geometry and Traffic Parameters on Railway Deterioration”, International Journal of Engineering, Volume 20, No.3, Dec 2007.
- [9]. Satish Chandra and M.M. Agarwal “Ebook of Railway Engineering” Oxford University press, 2007.
- [10]. Talukdar, K., Arulmozhi, U., Prabhakar, K. & Satyanarayan, 2006. Project Presentation Improvement of TGI Value by Computer Analysis. Ministry of Railways Indian Railways Institute of Civil Engineering, India.
- [11]. EL-Sibaie, M. & Zhang, Y., Objective Track Quality Indices Proceedings of 83 TRB Annual Meeting, Washington, D.C, 2004.
- [12]. Larsson, D. A study of the track degradation process related to changes in railway traffic. Division of Operation and Maintenance Engineering, Luleå University of Technology, Luleå, Sweden. ISSN: 1402-1757. 2004.
- [13]. Philip Laird and Max Michell “Interstate rail track upgrading options to 2014” 27th Australasian Transport Research Forum, Adelaide, 29 September – 1 October 2004.
- [14]. TN Ramachandaran, “Indian Railways Permanent Way manual”, Member/Engineering, Railway Board, Ministry of Railways, Government of India, Lucknow, 2004.
- [15]. Yu-Jiang Zhang, Magdy El-Sibaie & Sung Lee, “FRA Track Quality Indices and Distribution Characteristics”, AREMA 2004 Annual Conference, Nashville, September 19-22, 2004.
- [16]. Dahlberg, T. Railway track settlements – a literature review. Report for the EU project super track. Division of Solid Mechanics, IKP, Linköping University. 2003.
- [17]. Ferreira, L. and Murray, M. (1997). Modelling rail track deterioration and maintenance current practices and future needs. Transport Reviews, vol. 17, pp. 207- 221.
- [18]. Bing, A. J. & Gross, A., “Development of railway track degradation models”, Transportation Research Record 939, pp.27-31.1983.
- [19]. Alfred E. Fazio<sup>1</sup> and J. L. Corbin<sup>2</sup> “track quality index for high speed track (Reviewed by the Urban Transportation Division)
- [20]. Rengkui Liu, Ph.D.1; Peng Xu<sup>2</sup>; and Futian Wang, Ph.D.3 “Research on a Short-Range Prediction Model for Track Irregularity over Small Track Lengths”

dr.G.Venkata Rao." Study on Deviations and Settlements of Rails and Its Maintenance in Broad Gauge Railway Track." International Journal of Computational Engineering Research (IJCER), vol. 08, no. 04, 2018, pp. 34-40.